

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

**DATE:** February 12, 2013

**PAGE:** 1 OF 10

**FROM:** BOMBARDIER CUSTOMER SERVICES BUSINESS AIRCRAFT

### ADVISORY WIRE

**REFERENCE NO:** AW700-34-0346, Rev. 1

**SUBJECT:** Micro Air Data Computer - Altitude Split  
Troubleshooting Procedures and No Fault  
Found Update

**EFFECTIVITY:** Global Express aircraft (9002 to 9153)  
Global 5000 aircraft (9127 to 9311, 9315 to  
9379, 9382, 9383, 9389 to 9400, 9404 to 9431  
and 9998)  
Global Express XRS aircraft (9159 to 9312,  
9314 to 9380 and 9384 to 9429)

**ATA:** 34-11

**This Advisory Wire contains Operational and Maintenance Information**

This communication is available electronically at: <http://cic.bombardier.com/>. If you require technical information concerning this wire, please contact your Field Service Representative.

To obtain this document by e-mail or update your distribution profile, click here: <http://eepurl.com/IzvML>. To report transmission errors, please e-mail [bacs.e.dist@aero.bombardier.com](mailto:bacs.e.dist@aero.bombardier.com).

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 2 OF 10

### 1.0 REFERENCE:

1.1 Advisory Wire AW700-00-0178 No Fault Found Corrective Action Plan released 7 October 2005.

Reference 1.1, is located on CIC website (<http://www.cic.bombardier.com>) within the Technical Library > Advisory / Alert Wires > Global

### 2.0 INTRODUCTION:

This Advisory Wire (AW) revision 1 provides an update to Operators on the Micro Air Data Computer (MADC) and Advanced Micro Air Data Computer (AMADC) No Fault Found (NFF) initiative (Ref. 1.1) and new information related to ADC 3 FAIL and ADC 3 MISCOMP Crew Alerting System (CAS) messages trend and associated reference. This AW also provides acceptance criteria for altitude split, as well as updated Smart fix troubleshooting information.

### 3.0 DESCRIPTION:

In the AW700-00-0178 (Ref. 1.1), the MADC/ AMADC from Honeywell were identified as part of the top ten NFF for the Global Express. Following the introduction of some corrective action initiatives, the NFF rate has been reduced from as high as 65% to 46% as of today.

As part of the continuous NFF monitoring for the MADC (PN 7014700-628) and AMADC (PN 7030700-70708), Bombardier and Honeywell reviewed the details of all removals that were declared NFF to establish the trends and associated action plans. At the time of the release of the Advisory Wire (Ref. 1.1), the main NFF trend was related to altitude splits.

Since the majority of these NFF have been determined to be true NFF resulting from an improper troubleshooting, we have further improved guidelines and troubleshooting information. These improvements to troubleshooting information can be found in the Bombardier SmartFix Plus tool, in the Observed Faults > ATA 34 > "Altitude Indication Split/ALT Miscompare on PFD Altitude Tape". The latest updates are related to ADC

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 3 OF 10

strapping configuration check through the PMAT, Static Source Error Compensation (SSEC) configuration check and a simpler in flight recording table.

The following are more details on the current two (2) conditions that generate most NFF:

i) Altitude Split indications:

As a guideline, barometric altitude indications difference (altitude split) of up to 200 feet in flight between altimetry systems as selected for view on the Primary Flight Displays (PFD) may be acceptable and is still within the capability to perform RVSM operations.

For instance, the pilot PFD (ADC 1) and co-pilot PFD (ADC 2) are the usual flight information in view and used, making altitude splits between pilot and co-pilot PFD, the generally reported condition.

Since the altitude split value varies between one Global Express to another, it is important that operators/flight crews be familiar with the particular altitude split characteristic values between the different altimetry systems of their particular aircraft at specific speed, altitude, weight and flight phase.

Slow split increases over a certain period of time (i.e. months) from particular altitude split characteristic values are considered normal condition. This is attributed to the different drift characteristics between ADCs and Pitot/Static probe deterioration over time.

For this reason, we have checks in the TLMC Part 2 section 5-10-13 (RVSM qualified aircraft), where the ADCs are tested at regular intervals and the Pitot/Static probes have a life limit to ensure the system performance over time is maintained.

However, in a case where an altitude split significantly increases from particular altitude split characteristic values over a short period of time (same flight leg or from one flight leg to the next), or reaches 200 feet associated with the amber ALT Miscompare annunciation, it should be further

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 4 OF 10

investigated.

Any new altitude split value should always be compared with the normally acceptable particular altitude split characteristic values for that aircraft on similar flight profiles (speed, altitude, weight, flight phase).

In conclusion, it is highly recommended to follow all troubleshooting instructions in the Bombardier SmartFix Plus tool. Do not replace an MADC/AMADC that passes the AMM functional test, as this demonstrates proper static operation of the MADC/AMADC while the altitude split is most likely associated with aerodynamic effects that cannot be tested or reproduced by any ground test.

In such a case, replacing an MADC/AMADC will not correct the altitude split observed on the aircraft and when removed, will result in a No Fault Found (NFF).

ii) ADC3 FAIL and ADC3 MISCOMP CAS messages:

As part of the continuous NFF monitoring, Bombardier identified a trend associated with ADC3 FAIL and ADC3 MISCOMP (miscompare) CAS.

To provide additional troubleshooting information and collect data on those events to better understand the situation, Bombardier and Honeywell have made available a Troubleshooting Checklist (Ref. Appendix A) to be completed and returned to Bombardier when an ADC3 FAIL or ADC3 MISCOMP occurs. This will help us introduce a corrective action to reduce the NFF rate. The Troubleshooting Checklist (Ref. Appendix A) provides guidelines for in-flight procedures, additional troubleshooting and a flight test data sheet to be completed.

The ADC FAIL and MISCOMP are two (2) separate and unrelated CAS messages. For the ADC FAIL, the Integrated Avionics Computer (IAC) is not observing a valid Avionics Standard Communication Bus (ACSB) transmission from the MADC/AMADC or has flagged some of the data as invalid. An ADC FAIL should have an associated CAIMS or Fault Warning Computer (FWC) fault message and the associated SmartFix Plus

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

**DATE:** February 12, 2013

**PAGE:** 5 OF 10

troubleshooting should be followed.

The MISCOMP (miscompare) CAS message is monitored by the Automatic Flight Control System (AFCS) and indicates a discrepancy in the value of the data on one MADC/AMADC versus the other two. Therefore the miscompare is not necessarily due to a MADC/AMADC failure and troubleshooting per reference 1.2 should be performed.

#### **4.0 ACTION:**

Operators should be familiar with the altitude split characteristics and follow the associated SmartFix Plus troubleshooting recommendations. In cases of ADC3 FAIL or ADC3 MISCOMP message the MADC/AMADC Troubleshooting Checklist (Ref. 1.2) should be completed. The above recommendations should be completed prior to rejection of an MADC/AMADC.

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

<b>DATE:</b> February 12, 2013	<b>PAGE:</b> 6 OF 10
--------------------------------	----------------------

### Appendix A

#### **No 3 Micro Air Data Computer (MADC) or Advanced Micro Air Data Computer (AMADC)** **Troubleshooting Checklist** **Advisory Wire 700-34-0346 Rev 1 (ref 1.2)**

This checklist provides troubleshooting information and record information on the ADC3 FAIL and ADC3 MISCOMP CAS messages that may result NFF when MADC/ADC is replaced.

GEX A/C SN: \_\_\_\_\_  
 Contact Name and Phone: \_\_\_\_\_

ADC3 Part Number Removed: \_\_\_\_\_  
 ADC3 Unit Serial Number: \_\_\_\_\_

ADC3 Part Number Installed: \_\_\_\_\_  
 ADC3 Unit Serial Number: \_\_\_\_\_

Time/Date of the event: \_\_\_\_\_

#### **In Flight Procedures**

- If ADC3 is reported as fault, proceed as follow:
  - ADC3 MISCOMP CAS
    - Was the condition intermittent or continuous?
    - During the event, do an ADC reversion; visually check the value for ADC3 altitude or airspeed on pilot or copilot PFD and record ADC's 1, 2, 3 value for comparison:

	Altitude	Airspeed
ADC1		
ADC2		
ADC3		

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 7 OF 10

Added information as required:

---

---

---

---

---

- Was an altitude or airspeed split present at the time of the Miscompare? Yes\_\_\_ No\_\_\_  
If Yes:
  - Complete the attached Flight Test Data Sheet as much as practical.
  - ADC3 FAIL CAS
    - Was the condition intermittent or continuous?
    - During the event, do an ADC reversion; visually check the status of ADC3 on pilot or copilot PFD. Check the altitude and the airspeed tape for a red X across the tape. Check the vertical speed for the red VS check the pilot or copilot MFD MAP and PLAN format for SAT, TAS or TAT invalid data.
    - ADC FAIL CAS will be confirmed if the above show failure as well. Record details below.

Added information:

---

---

---

---

---

**On Ground Troubleshooting procedures:**

- CAIMS message at the time of the event:

Active	_____
Stored	_____
Flight	_____
Ground	_____

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

<b>DATE:</b> February 12, 2013	<b>PAGE:</b> 8 OF 10
--------------------------------	----------------------

- Perform troubleshooting in accordance to SmartFix Plus. Finding?

---



---



---



---

If the fault is intermittent and no fault is being returned to CAIMS, perform the following automatic test from the System Diagnostics / MADC / LRU TEST menu, in an attempt to isolate the fault condition:

TEST NAME	RESULT (Test Pass or Fault Code – four (4) digit)
ADC TEST	
TEMP PROBE INTERFACE TEST	
ADC SWITCH OUTPUTS TEST	
CONFIGURATION STATUS	

- Perform troubleshooting in accordance to SmartFix Plus. Finding?

---



---



---



---

**NOTE:**

If the two Functional Tests (Pitot-Static System, AMM Task 34-11-00-720-802 and Air Data Computer System, AMM Task 34-11-00-720-801) were successfully completed, the MADC/AMADC should not be replaced as a result of an altitude or airspeed split. Please contact your local Bombardier FSR for further troubleshooting.

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 9 OF 10

For an intermittent ADC3 MISCOMP, we recommend to swap ADC's and monitor the situation.

- Was the MADC/AMADC replaced as a result of performing a CAIMS or a CAS message Fault Isolation Task or following the Corrective Action from the IMT Fault Code Lookup table?

Yes\_\_\_ No\_\_\_ If Yes provide details (i.e. Task No.)

---

---

---

---

Details of the reason for removal:

---

---

---

---

- Any other parts (LRU) replaced on the aircraft during the troubleshooting of the same condition?

---

---

---

---

- Other useful comments (other maintenance performed on the A/C prior to this condition).

---

---

---

---

**Please send all this information's to Louis Martel by email at:**

Louis Martel  
Avionics Specialist – Global  
[louis.martel@aero.bombardier.com](mailto:louis.martel@aero.bombardier.com)

# ADVISORY WIRE

## AW700-34-0346, Rev. 1

DATE: February 12, 2013

PAGE: 10 OF 10

Flight Test Data Sheet  
 A/C \_\_\_ Date \_\_\_/\_\_\_/\_\_\_ Leg \_\_\_

MADC	Speed	Altitude	SAT	TAT	PEM/ Time	Fuel Load
1	200 Knot	15000				
2						
3						
EISI						
1	0.80 M	31000				
2						
3						
EISI						
1	0.85 M	31000				
2						
3						
EISI						
1	MMO	31000				
2						
3						
EISI						
1	0.80 M	41000				
2						
3						
EISI						
1	0.85 M	41000				
2						
3						
EISI						
1	0.85 M	47000				
2						
3						
EISI						