

Honeywell SERVICE INFORMATION LETTER

Engines, Systems & Services – Phoenix, Arizona

APPLICABLE:

**MAINTENANCE
& ENGINEERING**

**FLIGHT
OPERATIONS**

FOR ALL AIRFRAME MANUFACTURERS USING
GENERAL AVIATION, GENERAL PRODUCTS
AND/OR AUXILIARY POWER UNITS,
OWNER/OPERATORS, DISTRIBUTORS, SALES
AND SERVICE ORGANIZATIONS, AND FIELD
SERVICE REPRESENTATIVES.

Applicable To: Auxiliary Power Unit, RE220[GX]

Subject: Implementation of a Combustor Wash Program.

Purpose: To advise the field of recommended combustor wash program and availability of
Combustion Chamber Wash Kit (P/N 3700546-2).

Background: In service experience with the RE220[GX] APU has revealed that un-commanded
shutdowns may occur from combustor effusion hole plugging.

Effusion holes are used to provide cooling air to control combustor wall temperatures. Once
these holes become plugged, the cooling air instead flows to the combustion area, which
creates a lean fuel/air mixture. If the effusion holes are plugged severely enough, the lean
fuel/air mixture can cause the unit to flame out and shutdown. Honeywell Service
Information Letter, APU-80, discusses this condition in more detail.

Discussion: Honeywell has developed a combustor wash procedure designed to clear plugged
combustor effusion holes. This procedure documents all materials needed, tooling required
and the step by step process to perform the wash. To facilitate cleaning of the APU
combustor without removing the APU from the aircraft, Honeywell has developed the
Combustion Chamber Wash Kit, part number 3700546-2. This kit contains a two rotary
spray nozzles, two ignitor boss adapters, plastic tubing and one tubing adapter.

At the next revision of the AMM, the wash procedure will be included as an on-going
maintenance task (TASK 41-21-00-170-801). Wash kits will be provided to Bombardier
authorized Service Centers for combustor cleaning during scheduled maintenance intervals
or as required.

In order to preclude any un-commanded shutdowns driven by combustor clogging, for APU
S/Ns P-101 to P-285, Honeywell recommends the task be performed after every 1000 APU
operating hours for APUs incorporating combustor p/n WA3830474-2, (pre SB 49-7813) and
after every 2000 APU operating hours for APUs incorporating combustor p/n WE3830493-3,
(post SB 49-7813). For APU S/N P-286 and subsequent, Honeywell recommends the task
should be performed every 2000 APU operating hours.

However, operators should be aware that factors such as environmental conditions will
affect the rate at which the effusion holes will plug. Operators should review their APU
removal history in relation to combustor clogging events and determine the optimal wash
interval for their particular operations.

At the combustor wash event information pertinent to the aircraft and APU, should be
recorded. The information is as follows:

A/C Tail Number	APU Serial Number
A/C Hours	APU Hours
A/C Cycles	APU Cycles

Orig Apr 7/06

Revision 0

Copyright 2006 Honeywell International Inc. All rights reserved.

SIL NO. APU-106

Page 1 of 2

Honeywell SERVICE INFORMATION LETTER

Engines, Systems & Services – Phoenix, Arizona

This information, along with the wash date, should be forwarded to the noted Bombardier and Honeywell contacts listed below. It is imperative that operators provide this information, as it is required to track the effectiveness of the cleaning procedure.

Louis Legros
Propulsion Specialist
Customer Support Engineering, Business Aircraft
Côte-Vertu West
Dorval, Québec, Canada H4S 1Y9
Telephone: 514-855-8152
Fax: 514-855-7634
louis.legros@aero.bombardier.com

Joe Forbes
Honeywell Airframe Systems, Customer Service Engineer
Customer & Product Support
111 S. 34th Street
M/S 503-414
Phoenix, AZ 85034
Telephone: 602-231-4678
Fax: 602-231-1034
joe.forbes@honeyell.com