

ADVISORY WIRE

You.
First.

REFERENCE NO:	AW300-44-0243 Rev 1	INFORMATION TYPE:	Maintenance
ATA:	44-20	EFFECTIVITY:	Challenger 300 (20425) Challenger 350 (20501 – 20999)
SUBJECT:	nice® HD Blu-ray Player - Warning Message		

1. REFERENCE:

- 1.1. Lufthansa Technik Service Information Letter BDP3009-SIL44-0001 – Blu-ray: explanation of AACCS encryption warning message.
- 1.2. Lufthansa Technik Engineering Bulletin BDP3009-EB44-0518 – Blu-ray Disc Player AACCS-Key, update

NOTE: Documents are available at (<http://cic.bombardier.com>) in Technical Library> Service Bulletins> By Vendor>Lufthansa Technik.

2. INTRODUCTION:

The revision to this Advisory Wire (AW) is to inform operators that the Ref. 1.2 Engineering Bulletin (EB) has been released by Lufthansa Technik which introduces a software update to eliminate the warning message that may appear on monitors when playing Blu-ray discs.

3. DESCRIPTION:

The Advanced Access Content System (AACCS) warning message shown in Figure 1 of the Ref. 1.1 SIL has been reported to be displayed when trying to play some Blu-ray discs on aircraft equipped with the nice® HD Cabin Management System (CMS).

This message can occur especially if new movies are played in a Blu-ray player with old software. This behavior is part of the Blu-ray standard and does not represent a system malfunction or a design deficiency.

Blu-ray players affected by this behavior require a software update.

Lufthansa Technik has released the Ref. 1.2 Engineering Bulletin (EB), that provides instructions for the update and also provides a download link with user code and password, from which the required software needed to do the update can be obtained.

4. ACTION:

Operators should refer to the Ref. 1.2 EB if their Blu-ray player is affected by the AACCS warning message.