

SERVICE BULLETIN INFORMATION SHEET

MODEL BD-700-1A11 (BD-700)

ATA 27-31

FLIGHT CONTROLS

**REWORK – ELEVATOR CONTROL SYSTEM –
CORROSION PREVENTION OF ELEVATOR PCU, P/N GT411-3800-5 & -7,
ATTACHMENT FITTINGS AND SLOTTED ENTRY BEARINGS**

Service Bulletin No.: 700-1A11-27-025 **Issue:** Basic **Dated:** Oct 09/2008

The following data is supplied for information only. No revision to the Service Bulletin is necessary.

Keep this Information Sheet with subject Service Bulletin.

This Information Sheet is issued to change the effectivity statement in paragraph 1.A. of the Service Bulletin to reflect the changes given in Restriction And/Or Special Instruction (RSI), C-01463, Revision C.

The new effectivity is:

BD-700-1A11 aircraft, Serial No. **9127** to **9222**.

- NOTES:**
1. This Service Bulletin applies to PCUs, P/N GT411-3800-5 or GT411-3800-7. See Notes 4. and 5. below for exemptions.
 2. This Service Bulletin does not apply to PCUs P/N GT411-3800-9.
 3. This Service Bulletin applies to all PCUs, P/N GT411-3800 -7, with less than 1000 flight hours.
 4. The PCUs, P/N GT411-3800-7, with the Serial Nos below were upgraded to P/N GT411-3800-9 and are exempt from this Service Bulletin:

0004, 0005, 0006, 0010, 0014, 0016, 0017, 0028, 0043, 0096, 0098, 0102, 0106, 0118, 0123, 0132, 0150, 0168, 0170, 0177, 0184, 0200, 0231, 0246, 0254, 0269, 0371, 0432, 0440, 0446, 0452, 0455, 0458, 0507, 0508, 0540 and 0587.

BOMBARDIER
GLOBAL 5000

MODEL BD-700-1A11 (BD-700)

5. Any PCUs that have met the intent of this SB and Parker Service Bulletin 376100-27-306 through an SRPSA and do not have a limitation imposed by the REO for the SRPSA, do not need to do this Service Bulletin.

All other subsequent BD700-1A11 aircraft are scheduled for the modification (Ref Mod Summaries 700T02399) in production and in service by AMM practices for the GT411-3800-9 not covered in this

NOTE: The instructions given in this Service Bulletin are only applicable to the systems and parts installed at the time of delivery of the aircraft or as changed by Bombardier Aerospace Service Bulletin(s).

Before you do this bulletin, examine all STC, STA or equivalent action changes to make sure that this bulletin can be completed.