

**PACK LOOP B**

**Reporting LRU :** IASC 2  
**Total Loop Length :** 171 inches  
**Loop identification in the MDC :** MT141  
**Zero point :** Connector number MT141P1 under the precooler

**Message EICAS** **PACK LOOP FAIL** or **BLEED LOOP FAULT**

**MDC Fault code:**  
 - B3-008031 – PACK LOOP B SHORT CIRCUIT  
 - B3-008032 – PACK LOOP B OPEN CIRCUIT

Limit of each element	Fuselage Station	Percentage reported by MDC	Distance from zero point (inch)	Element	Detail
FROM	FS 816	0	0	MT141	Under the precooler
	FS 804	50	88		
TO	FS 765	100	171		Just downstream of lower FCV

**Schematics**

