

RH Bleed Loop (MT38, MT40, MT71): Single loop

Message Code: B3-007685

Red 'R BLEED LEAK' warning CAS message:
 IASC detected leak on right bleed ducting from RH IPV to RH ATS,
 HPGC interface, APU fire wall, CBV and upper FCV.

